

## **Press Release**

**Date:** 9 January 2012

### **A82 Glen Gloy – North of Spean Bridge Landslip affecting Abnormal Load Movements**

A landslip has recently occurred below the A82 Spean Bridge to Invergarry trunk road, at a point approximately 4 miles north of Spean Bridge, known as Glen Gloy.

With immediate effect, due to the geotechnical slope instability, abnormal loads exceeding 44 tonnes or with any individual axle load exceeding 11.5 tonnes are not permitted to travel on the affected section of the route. (A82 Spean Bridge to Invergarry).

Transport Managers should make early contact with Scotland TranServ the operating company responsible for the management and maintenance of the trunk road on 01738 455 300 (ask for Mr Keith Wigley Bridges Section).

Transport Managers and others engaged in the movement of affected abnormal loads should plan extra time for their journeys and pay attention to any advisory signs which will be in place throughout the works. For real time journey planning information visit [www.trafficscotland.org](http://www.trafficscotland.org)